

United States of America
Department of Transportation—Federal Aviation Administration
Supplemental Type Certificate

Number SH1968SO

This certificate, issued to Aeronautical Accessories, Inc.
P.O. Box 3689
Bristol, Tennessee 37625

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

Original Product—Type Certificate Number: H2SW

Make: Bell

Model: 206A, 206B, 206L, 206L-1, 206L-3, 206L-4

Description of Type Design Change: Installation of a Quick-Mount Kit to modify an existing Nose-Mounted Spectrolab Nightsun SX-16C Searchlight Assembly to a Quick-Mount configuration or a Quick-Mount Kit for the Spectrolab Nightsun SX-16 Searchlight Assembly to mount to the lower fuselage in accordance with Aeronautical Accessories, Inc. Report No. AA-86007, Drawing List, Quick-Mount Bracket Assembly for Bell 206A/B/L/L-1/L-3/L-4 Model Helicopters, Revision "L", dated June 22, 1994, or later FAA approved revision.

Limitations and Conditions: The approval of this change applies basically to Bell Models 206A/B/L/L-1/L-3/L-4. This approval should not be extended to other rotorcraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will produce no adverse effect upon the airworthiness of that rotorcraft. (Continued on Page 2)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: June 1, 1986

Date received:

Date of issuance: August 1, 1986

Date amended: October 9, 1990,
October 5, 1992, July 1, 1994

By direction of the Administrator



Roger D. Anderson
Roger D. Anderson
Manager, Atlanta Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation—Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Number SH1968SO

LIMITATIONS AND CONDITIONS (CONT.):

A copy of this STC and STC SH174WE must be included in the permanent records of each helicopter modified in accordance with this STC.

The FAA Approved Rotorcraft Flight Manual Supplements or later FAA Approved revisions are required as follows:

Quick-Mount Bracket Assembly for Spectrolab, Inc. Nightsun SX-16C Searchlight for Bell Model 206A/B, Report AA-86006, Revision "D", dated August 20, 1990, and Bell Model 206L/L-1/L-3/L-4, Report AA-86014, Revision "B", dated August 20, 1990.

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.
